


SIGNS FOR LIFTING WITH MOBILE CRANE



1. HOOK UP

Raised arm with index finger upwards. Circular movement of the hand.



2. HOOK DOWN

Arm and index finger pointing downwards. Circular movement of the hand.



3. HOOK SLOWLY UP

Raised arm. Small circular movements with the arm.



4. HOOK SLOWLY DOWN

Arm pointing downwards. Small circular movements with the hand.




5. BOOM UP

Horizontal arm. Thumb up.



6. BOOM DOWN

Horizontal arm. Thumb down.



7. SLEWING LEFT

Right arm horizontal. Open hand.




8. SLEWING RIGHT

Left arm horizontal. Open hand.



9. TELESCOPE OUT

Side movement outwards with both hands.



10. TELESCOPE IN

Side movement inwards with both hands.



11. MAIN WINCH

The hand raised above the top of the head.



12. AUXILIARY WINCH

Right lower arm upwards. Supported by left hand.



13. STOP

Horizontal arm turned in a curve forward and to the side.



14. FAST STOP

Both arms fast into horizontal position.



15. TRANSPORTATION

Circular movement with both hands.



16. SIGNAL NOT APPREHENDED

Side movement with the arm.

For signs, involving only one arm, either right or left arm can be used.

If fast lifting, lowering or transportation is needed the signs shall be given in a lively manner.

For combined lifting, with two cranes it must be decided and agreed how the lift shall be carried out and how the signs shall be given to both crane drivers.